

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA3005SO

*This certificate issued to* JR Aerosports, Ltd.  
850 Meacham Road  
Statesville, NC 28677

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 31 of the Federal Aviation Regulations.*

*Original Product - Type Certificate Number :* A14SO

*Make :* JR Aerosports, Ltd. (Sundance Balloons (US)) (Dawson Property LLC)

*Model :* Firefly 8B

*Description of Type Design Change:* Attachment of "Football Helmet" appendages in accordance with The Balloon Works Drawing No. B23287B, dated July 13, 1989.

*Limitations and Conditions:* This approval should not be extended to other balloons of this model on which other previously approved modifications are incorporated, unless it is determined by the installer that the interrelationship between this change and any other previously approved modifications will produce no adverse effect upon the airworthiness of that balloon. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*


*Date of application :* August 1, 1991

*Date of issuance :* August 20, 1991

*Date reissued :* June 24, 2005 (Reissued to Dawson Property Group LLC); June 29, 2006 (Reissued to Sundance Balloons (US)); August 11, 2009 (address change); September 16, 2010 (Reissued to JR Aerosports, Ltd.)

*Date amended :*

*By direction of the Administrator*

  
(Signature)

Melvin D. Taylor  
Manager, Atlanta Aircraft Certification Office



Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.