

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SR00149DE-D

This certificate, issued to **Air Methods Corp.
7301 S. Peoria
Englewood, CO 80112**

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 29 * of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet H13EU*

Original Product—Type Certificate Number: H9SW
Make: Bell Helicopter Textron
Model: 222, 222B, 222U, 230, and 430

Description of the Type Design Change:

Installation of an Air Methods Corporation Tail Stinger Attachment Modification in accordance with Air Methods Corporation Configuration Control Drawing No. 129-9015, Rev "-", dated April 13, 1995 or later FAA approved revision OR in accordance with Air Methods Corporation Master Data Index MDI 121-9014, Revision A, dated May 13, 2004 or later FAA approved revision.

Limitations and Conditions:

1. Compatibility of this design change with previously approved modifications must be determined by the installer.
2. A copy of this Certificate must be maintained as part of the permanent records for the modified rotorcraft.
3. Instructions for Continued Airworthiness shall be accomplished per Bell Helicopter Textron original Maintenance Manual and is required for this installation.
4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: March 1, 1995

Date reissued:

Date of issuance: April 14, 1995

Date amended: June 17, 2004



By direction of the Administrator

David T. Grossman

David T. Grossman (*Signature*) Rotorcraft Program Manager
Northwest Mountain Region
Denver Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.