

United States of America
Department of Transportation — Federal Aviation Administration
Supplemental Type Certificate

Number SH1414NM

This certificate, issued to Wesscam Camera Systems
717 Hampshire
San Francisco, CA

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 10 of the Civil Air Regulations.

Original Product — Type Certificate Number: H1IN
Make: Aerospatiale
Model: SA315B

Description of Type Design Change: Installation of "Wesscam" Camera Control Console in place of left front seat; Servotec AGL-8098 camera mount outriggers, left and right; Canadian Westinghouse "Wesscam" gyro stabilized HC32 or 33 camera assembly contained within a plastic sphere, and associated hardware in accordance with Servotec Report No. AGL-TR-269.

Limitations and Conditions: Approval of this change in type design applies to the above model helicopter only. This approval should not be extended to helicopters of this model on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that helicopter. A copy of this Certificate, Addendum and Rotorcraft Flight Manual Supplement shall be maintained as part of the permanent records for the modified aircraft. (See Addendum Page 3, attached)
This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 22, 1981

Date reissued:

Date of issuance: January 13, 1982

Date amended:



By direction of the Administrator

T. J. Jacobsen
(Signature)

Chief, Seattle Area Aircraft
Certification Office, ANM-100S

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.