

Supplemental Type Certificate

Number SR09175RC

This Certificate issued to LifePort, Inc.
1610 Heritage Street
Woodland, Washington 98674

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations. *Certification basis is set forth in Type Certificate Data Sheet H2SW and Equivalent Level of Safety (ELOS) Memorandum Number ELOS SA11295LA-R/C-1 dated July 25, 2006*

Original Product Type Certificate Number: H2SW

Make: Bell

Model: 407

Description of Type Design Change: Installation of a LifePort Air Medical Carriage System in accordance with LifePort, Inc. Master Drawing List for Bell 407 Carriage Installation EGR-511-00, Revision N, dated November 7, 1997 or later FAA approved revision. FAA Approved Rotorcraft Flight Manual Supplement No. EGR-511-16, dated February 19, 1999, or later FAA approved revision is required as part of this installation.

Limitations and Conditions: The installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. The approval of this modification applies to the above noted airplane model series only. A copy of this STC must be included in the permanent records of the modified aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 29, 1996

Date reissued: June 14, 1999

Date of issuance: October 16, 1997

Date amended: July 31, 2006



By direction of the Administrator

Original signed by Greg DiLibero

(Signature)

Manager, Airframe Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.