

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SR01295AT-D

*This certificate issued to*

Bell Helicopter Textron, Inc.  
441 Industrial Park Road  
Piney Flats, TN 37686

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.*

*Original Product -- Type Certificate Number :* H2SW  
*Make :* Bell Helicopter Textron Canada  
*Model :* 407

*Description of Type Design Change:*

External Hoist Kits and Hoist Retrofit Kit in accordance with Aeronautical Accessories, Inc. Drawing List, Report No. AA-97005, Rev. H, dated May 17, 2006, or later DAS approved revision. For External Hoist Kit, Installation Instructions Report No. AA-97006, Rev. K, dated March 22, 2004 or later DAS approved revision. For Hoist Retrofit Kit 407-998-001, Installation Instructions Report AA-06055, No Revision, dated May 16, 2006 or later DAS approved revision.

*Limitations and Conditions:*

(See continuation sheet 3 of 3)

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application :* March 28, 1996

*Date reissued :* October 10, 2011

*Date of issuance :* July 02, 1997

*Date amended :* June 02, 2006



*By direction of the Administrator*

\_\_\_\_\_  
(Signature)  
Scott A. Horn, Acting Manager,  
Rotorcraft Certification Office,  
Southwest Region

\_\_\_\_\_  
(Title)

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**  
(Continuation Sheet)

United States of America  
Department of Transportation -- Federal Aviation Administration

**Supplemental Type Certificate**  
(Continuation Sheet)

*Number* SR01295AT-D

Date of Issuance: July 02, 1997

Date Amended: June 02, 2006

Date of Reissuance: October 10, 2011

*Limitations and Conditions* (Continued):

For External Hoist Kits, Instructions for Continued Airworthiness, Aeronautical Accessories, Inc. Report AA-97044, Revision B, dated March 31, 2004, or later FAA accepted revisions and Rotorcraft Flight Manual Supplement, Aeronautical Accessories, Inc. Report AA-97007, Rev. C, October 21, 2002, or later DAS approved revisions are required.

For Hoist Retrofit Kit 407-998-001, installation of External Hoist Kit with Hoist Assembly BL-16600-170 in accordance with STC SR01295AT-D is required. Rotorcraft Flight Manual Supplement, Aeronautical Accessories, Inc. Report AA-06052, No. Rev., dated June 2, 2006, or later DAS approved revisions and Rotorcraft Flight Manual Supplement, Aeronautical Accessories, Inc. Report AA-97007, Rev. C, October 21, 2002, or later DAS approved revisions are required.

The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

-END-