

United States Of America  
Department of Transportation - Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* ST10203SC

*This Certificate issued to* Hawker Beechcraft Services, Inc.  
10440 John Cape Road  
San Antonio, TX 78216

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

*Original Product Type Certificate Number :* A16SW  
*Make :* Raytheon Aircraft Co.  
*Model :* 400; MU-300-10

*Description of Type Design Change:*

Installation of a Honeywell MK VIII Enhanced Ground Proximity Warning System (EGPWS) and Honeywell RDR 2100 Weather Radar in accordance with Master Drawing List No. RAS25-6-000001, Rev. D, dated October 20, 2003, or later FAA approved revision. FAA approved Airplane Flight Manual Supplement RAS25-6-000011, Rev. I.R., dated November 13, 2003, or later FAA approved revision is required.

*Limitations and Conditions:*

The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application :* August 12, 2003

*Date reissued :* April 24, 2007

*Date of issuance :* November 13, 2003

*Date amended :*



*By direction of the Administrator*

\_\_\_\_\_  
(Signature)  
S. Frances Cox, Manager  
Special Certification Office,  
Southwest Region

\_\_\_\_\_  
(Title)

United States Of America  
Department of Transportation - Federal Aviation Administration  
**Supplemental Type Certificate**  
(Continuation Sheet)

---

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*