

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SR09441RC

PM: CCH
PN: SA3343RC-R

This certificate issued to

HELIFAB, Inc.
1318 Smede Hwy
Broussard, LA 70518

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 6 of the Civil Air Regulations.

Original Product -- Type Certificate Number : H2SW
Make : Bell Helicopter Textron Canada
Model : 206L-1, 206L-3, 206L-4

Description of Type Design Change: 2501-1 and 2501-2 non-reclining Litter Installations in accordance with Helifab, Inc., Master Drawing and Document List HF-206-DL-100, Revision A, dated July 13, 2005, or later FAA approved revision

2501-3 reclining Litter Installation, 2511-1 or 2521-1 litter installations in accordance with Helifab, Inc., Master Drawing List HF-206-DL-100, Revision K, dated January 20, 2012, or later FAA approved revision.

For installation of Litter Kits the following drawings are required: Helifab, Inc. drawing HF-206-EMS-2000, Revision D, dated November 07, 2011, Helifab, Inc. drawing 2101, Revision A, dated November 16, 2007, and Helifab, Inc. drawing 2301, Revision IR, dated February 1, 2005, or later FAA approved revisions.

Limitations and Conditions:

- 1) FAA approved blackout curtains must be installed for EMS Night Operations. FAA approved Rotorcraft Flight Manual Supplement (RFMS) HF-206-FMS-001, Rev 2 dated October 7, 2009, or later FAA approved RFMS is required

(See continuation sheet 3 of 3)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : February 16, 2005

Date reissued :

Date of issuance : August 05, 2005

Date amended : October 07, 2009;
February 24, 2012



By direction of the Administrator

(Signature)
Scott A. Horn, Acting Manager
Rotorcraft Certification Office
Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate
(Continuation Sheet)

Number SR09441RC

Date of Issuance: August 05, 2005

Date Amended: February 24, 2012

Limitations and Conditions (Continued):

- 2) Instructions for Continued Airworthiness, Helifab, Inc. Report No. HF-206-ICA-Stretcher-1, Revision C, dated November 7, 2011, or later FAA accepted revision is required for the installations.
- 3) Compatibility of this design change with previously approved modifications must be determined by the installer.
- 4) If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

Certification Basis: Same as Type Certification Data Sheet H2SW except for an Equivalent Safety Finding has been made for the following regulation:

14 CFR Part 27 at Amendment 27-37 for §27.805(a) and §27.805(b), and 14 CFR Part 27 at Amendment 27-26 for §27.807(a) and §27.807(b)(1), §27.807(b)(2), and §27.807(b)(3) documented in ELOS Memo SA2975RC-R/C-1.