

United States of America
Department of Transportation Federal Aviation Administration
Supplemental Type Certificate

Number SR00875SE

This certificate, issued to

Columbia Helicopters, Inc.
P.O. Box 3500
Portland, OR 97208

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 7 and 10 of the Civil Air Regulations.

Original Product—Type Certificate Number: H9EA
Make: Boeing
Model: Vertol 234 Series

Description of the Type Design Change: Installation of Honeywell Solid State Flight Data Recorder (SSFDR) and Teledyne Digital Flight Data Acquisition Unit (DFDAU) per Columbia Helicopters, Inc., Master Drawing List 99-AVI-0221, Revision B, dated February 14, 2001, or later FAA approved revision.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft only. This approval should not be extended to aircraft of these models on which other previously approved modifications are incorporated unless it is determined that the relationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this certificate shall be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission. FAA Approved Flight Manual Supplement No. 99-AVI-0621, Revision: Basic, February 16, 2001 is a required part of this STC.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 22, 1999

Date reissued:

Date of issuance: February 16, 2001

Date amended:

By direction of the Administrator



(Signature)
Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.