

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number SA00555DE

This Certificate issued to Aircraft Restoration Corporation
3410 West 1010 South
Provo, Utah 84601

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product Type Certificate Number: A20SO; A8EA

Make: Piper

Model: PA-31; PA-31P, PA-31T, PA-31T1, PA-31T2

Description of Type Design Change: Replacement of the inboard main landing gear door with an aerodynamic fairing in accordance with Aircraft Restoration Corporation Master Drawing List No. MDL-85280-01, Revision A, dated June 04, 2004, FAA approved June 21, 2004, or later FAA approved revision.

Limitations and Conditions:

1. Instructions for Continued Airworthiness, Aircraft Restoration Corporation Report No. ICA-85280-01 dated February 13, 2004, or later FAA accepted revision is required for this installation.
2. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that aircraft.
3. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 05, 2003

Date reissued: June 7, 2007, February 21, 2008

Date of issuance: June 21, 2004

Date amended:



By direction of the Administrator

(Signature)
Manager, Airframe Branch
Los Angeles Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Number (STC No.)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.