

Supplemental Type Certificate

Number SA01499SE

This certificate, issued to

**Gold Coast Aviation Service Inc.
45 Mortensen Avenue - Municipal Airport
Salinas, CA 93905**

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 3 of the Civil Aviation Regulations.

<i>Original Product—Type Certificate Number:</i>	A-799
<i>Make:</i>	Cessna
<i>Model:</i>	170A, 170B

Description of the Type Design Change: Remove a Hartzell model HC-C2YR-1B/7666-2 propeller on the above model aircraft, and install a McCauly model B3D36C424/74SA-0 propeller per Gold Coast Aviation Service Inc. Report GCA170-2-04, Revision 0, dated November 22, 2004, or later FAA approved revision to this report.

Limitations and Conditions: In order for an airplane to be eligible for modification under this STC, Avcon STC SA806CE must either have been incorporated on the subject airplane, or must be incorporated concurrently.

Approval of this change in type design applies to the above model airplanes only. This approval should not be extended to other airplanes on which other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of that airplane. A copy of this certificate and Airplane Flight Manual Supplement GCA170-3-04 dated January 7, 2005 or later FAA approved revision must be maintained as part of the permanent records for the modified airplane. The propeller must be maintained in accordance with the approved manufacturer's manual, and other approved instructions.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 22, 2004

Date reissued:

Date of issuance: January 18, 2005

Date amended:



By direction of the Administrator

(Signature)
Acting Manager, Seattle Aircraft
Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.