

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number SR02494NY

This certificate issued to ECT Industries
Zone d'activite de la Plaine
07130 Soyons France

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: H9EU
Make: Eurocopter France
Model: AS350B3

Description of Type Design Change:

Installation of DMS ARINC data recorder in accordance with ECT Industries Definition File Number DD-0074-XX-82, Revision 03, approved October 20, 2006, or later EASA approved revision.

Limitations and Conditions:

1. This approval is limited to only the installation made in Eurocopter model AS350B3 with part number REC-AR0-TT-OO.
2. The following are required for this installation:
 - a. ECT Industries Installation Instructions number IM-0078-XX-82-EN, Revision 00, dated November 28, 2006.
 - b. ECT Industries Maintenance Manual number MM1-0077-XX-82-EN, Revision 04, dated November 14, 2007.
 - c. ECT Industries Operating Manual number MUL-0076-04-82-UK, Revision 04, dated November 21, 2006.
3. The installer must determine whether this design change is compatible with previously approved modifications.
4. If the holder agrees to permit another person to use the certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 8, 2007

Date reissued:

Date of issuance: January 3, 2008

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.