

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number ST02676NY

This certificate issued to DECA Aviation Engineering Limited
200-7050 Telford Way
Mississauga, Ontario
Canada L5S 1V7

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: A21EA
Make: Bombardier
Model: CL-600-2A12

Description of Type Design Change:

19 passenger interior configuration installation must proceed in accordance with DECA Aviation Modification Summary MS06134, Revision 1 or later Transport Canada approved revisions.

STC SA4377SW and SA4363SW must be installed prior to or concurrently with this STC.

This design change does not require additional Instructions for Continued Airworthiness. The existing Instructions for Continued Airworthiness as defined by the aircraft type design remain applicable.

Limitations and conditions (Continued):

1. Descriptive data pertaining to this design change are considered inadequate for duplication in other products. This approval is limited to only the installation made Bombardier CL600-2A12, serial number 3027. This STC does not permit manufacturing of parts for multiple installations.
2. This aircraft is not certified for ditching since compliance with Far 25.801(a) has not been demonstrated.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: September 05, 2008

Date reissued:

Date of issuance: February 09, 2009

Date amended:



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.