

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate

Number SR09444RC

This certificate issued to

SAGEM Avionics, Inc.
2701 Forum Drive
Grand Prairie, TX 75052-7099

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 27 of the Federal Aviation Regulations.

Original Product -- Type Certificate Number: H2SW
Make: Bell Helicopter Textron Canada Limited
Model: 206B

Description of Type Design Change:

Installation of a SAGEM Automatic Flight Control System in accordance with Heritage Aviation Ltd. Drawing 100-15001, Revision A, "Master Drawing List, Automatic Flight Control System - BHT206B", dated August 26, 2005, or later FAA approved revision.

Limitations and Conditions:

(See continuation sheet 3 of 3)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: October 19, 2004

Date reissued: May 10, 2007

Date of issuance: August 29, 2005

Date amended:



By direction of the Administrator

(Signature)
Lance T. Gant, Manager
Rotorcraft Certification Office,
Southwest Region

(Title)

United States of America
Department of Transportation -- Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate
(Continuation Sheet)

Number SR09444RC

Date of Issuance: August 29, 2005

Reissuance Date: May 10, 2007

Limitations and Conditions (Continued):

Rotorcraft Flight Manual Supplement, Heritage Aviation Ltd. Drawing 109-65004, "Rotorcraft Flight Manual Supplement for BHTI Model 206B with SAGEM Two-Axis Automatic Flight Control System", dated August 29, 2005, or later FAA approved revision is required for this installation. Instructions for Continued Airworthiness, Heritage Aviation Ltd. Drawing 104-75001, Revision -, "Instructions for Continued Airworthiness SAGEM Two-Axis Automatic Flight Control System", dated May 18, 2005 or later FAA accepted revision is required for this installation. Installation of the SAGEM Flight Display System per STC ST2776RC-R is required. The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

-END-