

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number SA09565SC

This Certificate issued to Intercontinental Jet Service Corporation
a Delaware Corporation
3322 N. 74th East Avenue
Tulsa, OK 74115

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product Type Certificate Number : [See attached FAA approved model list (AML)]

Make : for list of approved models and applicable

Model : airworthiness regulations]

Description of Type Design Change: Installation of TPE331-10AV-511M engines in accordance with "STC Instructions", Revision 1, dated January 4, 1999, and "Engine Installation, Turboprop TPE331-10AV", Drawing No. 3108201, dated October 20, 1997, or later FAA approved revision. FAA approved Flight Manual Supplement dated July 22, 1999, or later FAA approved revision required.

Limitations and Conditions: Installation only on aircraft which have TPE331-6-251M or -252M engines installed. Hartzell Propeller, model number HC-B3TN-5()/T10178NS()-11R, with "N" style shot peened blades will be used with the replacement engine. The propeller diameter limits are 90.375 to 89.375 inches. The installer must determine whether this design change is compatible with previously approved modifications. If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : September 21, 1998

Date reissued : 10/29/99; 9/11/06; 3/30/12

Date of issuance : July 22, 1999

Date amended :



By direction of the Administrator

(Signature)

M. Monica Merritt, Manager
Airplane Certification Office,
Southwest Region

(Title)