

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

IMPORT

Number ST02252NY

This certificate issued to
Bombardier Aerospace
200 Cote Vertu Road West
Dorval, Québec
H4S 2A3, Canada

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified herein meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product -- Type Certificate *Number:* T00005NY
Make: Bombardier
Model: BD-100-1A10

Description of Type Design Change:

Installation of Artex ELT C406-N with a Navigation Interface in accordance with Aero Consulting Services Ltd. Modification Data Summary (MDS) Report Number E618000, Revision D; dated September 09, 2010; or later Transport Canada approved revision.

Limitations and Conditions:

- Maintenance must be in accordance with Instruction for Continued Airworthiness, document number:
 - RAL-BV100-25601-IFCA, Revision F1 dated December 5, 2005; and HC25615000-IFCA Revision A or later Transport Canada accepted revision for Aircraft up to and including serial number 20099.
 - RAL-BV100-25601-IFCA, Revision F1 dated December 5, 2005 or later Transport Canada accepted revision for Aircraft serial number 20100 and subsequent.
- The installer must determine whether this design change is compatible with previously approved modifications.
- If the holder agrees to permit another person to use this certificate to alter a product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 18, 2006

Date reissued:

Date of issuance: April 17, 2006

Date amended: February 16, 2011



By direction of the Administrator

(Signature)

Anthony Socias
Manager
New York Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.