

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate

Number ST00087LA

This Certificate issued to Rockwell Collins, Inc.
1733 Alton Parkway
Irvine, California 92606

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*
*(For Certification basis see Type Certificate Data Sheet A35EU)

Original Product Type Certificate Number: A35EU
Make: Airbus
Model: A310-300

Description of Type Design Change: Installation of Sony Trans Com Video Entertainment System Part Number 985-0173-006 Revision D, in accordance with FAA approved Sony Trans Com Drawing List 060-3687-000 Revision A, dated 3/28/95 of the Index List 062-0132-000, Rev N/C dated June 28, 1995 or later FAA approved revisions.

Limitations and Conditions: This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. Refer to the appropriate section of Sony Trans Com Index List Document for additional limitations. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: March 8, 1995

Reissue Date: August 30, 2000; May 30, 2006,
August 10, 2016

Date of issuance: July 6, 1995

Date amended:



By direction of the Administrator

(Signature)
Manager, Technical & Administrative Support
Staff, Los Angeles Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.