

Supplemental Type Certificate

Number ST01547LA

This Certificate issued to Teledyne Controls
501 Continental Boulevard
El Segundo, CA 90245

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.*

**for certification basis see TCDS T00003NY*

Original Product Type Certificate Number: T00003NY

Make: Bombardier, Inc.

Model: BD-700-1A10 Series

Description of Type Design Change: Installation of EMS Technologies High Speed Data Satellite Communications System HSD-64 and HSD-128 in accordance with FAA Approved Master Data List No. MDL2246759, Revision “-“, dated August 1, 2003, or later FAA approved revisions.

Limitations and Conditions: This installation should not be incorporated in any aircraft unless it is determined that the interrelationship between this installation and any previously approved configuration will not introduce any adverse effect upon the airworthiness of the aircraft. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data, which is the basis for approval, shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: April 21, 2003

Date reissued: October 4, 2012

Date of issuance: October 14, 2003

Date amended:

By direction of the Administrator



(Signature)

Haifa Haj-Eid
Supervisor, Technical and Administrative Support Staff
Los Angeles Aircraft Certification Office

(Title)

United States Of America
Department of Transportation - Federal Aviation Administration
Supplemental Type Certificate
(Continuation Sheet)

NOTE:

DO NOT DELETE THIS PAGE.

DO NOT ADD ANY DATA TO THIS PAGE.

THIS PAGE IS FOR PAGE NUMBERING PURPOSES,
PLEASE DISCARD PRINTED COPY.

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.