

United States of America
Department of Transportation -- Federal Aviation Administration

Supplemental Type Certificate

Number SA00004WI

This certificate, issued to Rockwell Collins, Inc.
400 Collins Road NE, MS 164-100
Cedar Rapids, IA 52498

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product - Type Certificate Number : A24CE
Make : Beech
Model : B300, B300C

Description of Type Design Change: Installation of a Universal Navigation Corp. CVR-80 Cockpit Voice Recorder System. Data required: (1) Collins Drawing Index 992-1947-001, no revision, dated April 14, 1992. (2) FAA Approved Flight Manual Supplement No. ACC-92-33, for the Beech Model B300/B300C airplane, no revision, dated October 26, 1992, or later FAA approved revisions of (1) or (2).

Limitations and Conditions: (1) This approval should not be extended to other specific airplanes of these models on which other previously approved modifications are incorporated, unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that airplane. (2) If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : April 9, 1992

Date reissued : August 22, 1997

Date of issuance : October 26, 1992

Date amended :



By direction of the Administrator

Dale R. Koonts

(Signature)

Dale R. Koonts

Manager, DAS-3CE

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.